

## **Right-Angle Shapes, MIL style**


• Helashrink 1100 Series, with rib

## **Features and Benefits**

• With circular grooved adaptor for strain relief







b: Fully recovered form (after heating) 1108-4 supplied / fully recovered.

a: Expanded form (supplied)

ТҮРЕ	ØH min. a	ØH max. b	ØJ min. a	ØJ max. b	P ± 10%	R ± 10%	HW ± 20%	JW ± 30%	V max.	T ± 20%	M nom.	S nom.	Article-No.
1108-4-G	16.5	7.9	16.5	3.8	17.3	20.1	1.0	1.6	3.3	1.0	15.2	5.1	411-08480

All dimensions in mm. Subject to technical changes.

For these moulded shapes a wide range of material / adhesive combinations are available. Please refer to the moulded shapes catalogue.

## **Right-Angle Shapes**


• Helashrink 1100 Series, without rib

## **Features and Benefits**


- Strain relief for connector cable
- Easy re-entry for repair when combined with hot melt adhesive




1108-1 supplied / fully recovered.



a: Expanded form (supplied)





ТҮРЕ	ØH min. a	ØH max. b	ØJ min. a	ØJ max. b	P ± 10%	R ± 10%	HW ± 20%	JW ± 30%	M nom.	S nom.	Article-No.
1108-1-G	16.5	7.9	16.5	3.8	17.3	20.1	1.0	1.6	15.2	5.1	411-08180

All dimensions in mm. Subject to technical changes.

For these moulded shapes a wide range of material / adhesive combinations are available. Please refer to the moulded shapes catalogue.

221